

CONVENTIONAL PRINTING METHODS PER FACESTOCK

Facestock	Offset		Letterpress		Flexography			Screen printing		Thermal Transfer	Hot stamping
	Conventional	UV	Conventional	UV	Water-based	Solvent-based	UV	Conventional	UV		
Offset	●	●	●	●	●	●	●	●	●	●	●
Laser	●	●	●	●	●	●	●	●	●	●	●
Matt	●	●	●	●	●	●	●	●	●	●	●
Gloss 60	●	●	●	●	●	●	●	●	●	●	●
Gloss 80-150	●	●	●	●	●	●	●	●	●	●	●
Gloss GP	●	●	●	●	●	●	●	●	●	●	●
Art	●	●	●	●	●	●	●	●	●	●	●
Cardboard	●	●	●	●	●	●	●	●	●	●	●
Embossed Toile WS		●					●				
Embossed Martelé WS		●		●			●				
Laid WS	●	●	●	●	●	●	●	●	●	●	●
Vintack WS	●	●	●	●	●	●	●	●	●	●	●
Thermal Eco	●	●	●	●	●	●	●	●	●	●	●
Thermal Top+	●	●	●	●	●	●	●	●	●	●	●
Glitter WS		●		●	●	●	●				
High Gloss	●	●	●	●	●	●	●	●	●	●	●
High Gloss WS	●	●	●	●	●	●	●	●	●	●	●
Metal HG WS	●	●	●	●	●	●	●	●	●	●	●
Foil	●	●	●	●	●	●	●	●	●	●	●
Colour Matt	●	●	●	●	●	●	●	●	●	●	●
Fluo	●	●	●	●	●	●	●	●	●	●	●
Carbonless CF	●	●	●	●	●	○	●	○	○	○	○

CONVENTIONAL PRINTING METHODS PER FACESTOCK

Facestock	Offset		Letterpress		Flexography			Screen printing		Thermal Transfer	Hot stamping
	Conventional	UV	Conventional	UV	Water-based	Solvent-based	UV	Conventional	UV		
Acetate	●	●	●	●	●	●	●	●	●	●	●
PE White	●	●	●	●	●	●	●	●	●	●	●
PE Clear	●	●	●	●	●	●	●	●	●	●	●
PP White	●	●	●	●	●	●	●	●	●	●	●
PP Clear	●	●	●	●	●	●	●	●	●	●	●
PP Pearl	●	●	●	●	●	●	●	●	●	●	●
PVC White	●	●	●	●	●	●	●	●	●	●	●
PVC Clear	●	●	●	●	●	●	●	●	●	●	●

Last update: **May 2018**

All this information is based on our experience and is not a guarantee.

Symbols
● Suitable
● With caution
● Not suitable
○ Not applicable